

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments
1	BRS	L1	1	((method or process) and hose and fluoropolymer and jacket and (etching or etched or etch) and (extruded or extrusion or extruding) and (corrugation or corrugating)).clm.	US- PGPUB	2008/04/28 12:44	

	Error Definition	Errors
1		